



ECHLIN®

Did You Know?

Ford Power Stroke Injectors

Ford Truck 1994-1998

Caution: Some 7.3L diesel engines may exhibit a rough idle and engine miss due to injector bore scuffing. This is due to insufficient lubricity additive in some fuels.

NAPA Echlin recommends adding a bottle of injector lubricator (Siloo-6AA or Lucas 10003) to a full tank prior to replacing injectors.

NAPA Echlin also offers glow plug controller, glow plug relays, diesel injection pumps and injector installation tools for light duty applications.



2-17621 / 2-17626

Contact NAPA for all your diesel replacement parts.

NAPA Echlin
LOOKS RIGHT. FITS RIGHT. PERFORMS RIGHT.

THE BEAR IS BACK



EC005-05