

Crankshaft Sensors



CSS21176

Toyota Highlander
(2022-17)
VIO: 1.2M



CSS2074

RAM 2500 / 3500
(2024-19)
VIO: 460K



CSS9296

Genesis / KIA Cars
(2023-18)
VIO: 52K



Camshaft Sensors



CSS2033

Hyundai Cars & SUVs
(2023-2019)
VIO: 1.3M



CSS2080

(Intake)

Volkswagen Cars & SUVs
(2023-22)
VIO: 178K



CSS2077

(Exhaust)



CSS2082

(Intake Rear)



CSS2079

(Intake Front)



CSS2078

(Exhaust)

Genesis / KIA
Cars, SUVs & Vans
(2023-21)
VIO: 100K





ECHLIN

NEW PARTS SPOTLIGHT

UP AND COMING



These Camshaft and Crankshaft Sensors have been released in the past few years and are increasing in popularity



CSS2114

Camshaft Sensor
GM Cars, Trucks & SUVs
(2022-16)
VIO: 1.6M



CSS2012

Camshaft Sensor
Subaru Cars & SUVs
(2022-17)
VIO: 1.6M



CSS1689

Camshaft Sensor
Ford Cars, Trucks, SUVs & Vans
(2020-19)
VIO: 970K



CSS2019

Camshaft Sensor
Nissan Cars & SUVs
(2021-19)
VIO: 1M



CSS2032

Crankshaft Sensor
Toyota Cars, SUVs & Vans
(2021-18)
VIO: 3.8M



CSS1662

Crankshaft Sensor
Lexus / Toyota Cars, SUVs & Vans
(2023-18)
VIO: 3.5M



CSS1695

Crankshaft Sensor
GM 2500 / 3500
(2021-17)
VIO: 615K



CSS2026

Crankshaft Sensor
Alfa Romeo / Fiat / Jeep Cars & SUVs
(2021-17)
VIO: 510K



CSS1682

Crankshaft Sensor
GM 1500 Trucks
(2020-16)
VIO: 1.4M



ECHLIN

LOOKS RIGHT. FITS RIGHT. PERFORMS RIGHT.

NAPAEchlin.com