

Transfer Case Gear Repair Kit

New Product Category

Tech Expert's new Transfer Case Gear Repair Kit comes complete with everything you need to replace only the failed transfer case motor gear instead of the entire assembly. Providing a re-engineered alternative to the plastic OE gear, our kit includes an upgraded metal gear that better protects against wearing and breaking. The plastic OE gear is a common failure for certain BMW applications between 80,000 and 120,000 miles.



TCG700
BMW 2010-04
VIO Over 250,000

Windshield Wiper Motor

New Product Category

Faulty windshield wiper motors can cause driving issues during inclement weather. To provide high-quality replacements for this important safety category, Tech Expert™ has introduced a new line of Windshield Wiper Motors for Hyundai and Kia applications. Each one is an Exact-Match, Direct-Fit OE replacement to ensure proper fit, form, and function.



WWM500
Hyundai Sonata 2010-06
VIO Over 580,000



WWM506
Hyundai Santa Fe 2006-01
VIO Over 390,000



WWM511
Kia Sorento 2009-03
VIO Over 280,000

Accelerator Pedal Sensor Repair Kit

1 New SKU Available



APR103
Chevy Trucks 2002-94
VIO Over 5.2 Million

Air Door Actuator

5 New SKUs Available



ADA223
Chevrolet Express 2015-03
GMC Savana 2015-03
VIO Over 1.1 Million

Air Suspension Solenoid

1 New SKU Available



ASP102
Ford Expedition 2006-03
Lincoln Navigator 2006-03
VIO Over 660,000

Electronic Throttle Body

1 New SKU Available



ETB510
Lexus ES300 2003-01
VIO Over 130,000

Engine Variable Valve Timing Spool

2 New SKUs Available



VSG505
Honda Civic 2005-96
Honda Civic del Sol
1997-96
VIO Over 2.0 Million

Headlight Level Sensor

7 New SKUs Available



HLS576
Mazda 3 2015-14
Mazda 6 2015-14
Mazda CX-5 2015-13
VIO Over 530,000