



## TECH EXPERT™ DISA Valve Repair Kits

REPLACE FAILED  
FLAP ONLY



DSA700 / DSA701 / DSA702  
BMW (12-97)  
VIO over 1.5 Million

### Quick Facts



Includes flap, flap driver, mounting pin and clip, removal screw, and O-ring



Replace failed DISA valve flap only, not full DISA valve assembly



Multiple kits available for wide range of BMW applications

[TECHEXPERTPARTS.COM](http://TECHEXPERTPARTS.COM)

*Expert Solutions for Professional Technicians™*


## Replace the Flap, Not the DISA Valve

**The Problem:** The Differentiated Intake System Actuator (DISA) valve flap or driver can become stripped over time. When that happens, the vehicle may experience a rough idle, a loss of power, or display a diagnostic trouble code. Repair requires replacing the entire expensive assembly.

**Our Response:** To save customers money, TECH EXPERT™ DISA Valve Repair Kits include everything needed to replace only the failed flap instead of the entire DISA valve assembly. Each kit comes complete with a new flap, a flap driver, a mounting pin and clip, a screw to assist with removing the damaged unit, and an O-ring to prevent vacuum leaks.

**When DISA valve flaps fail on certain BMW applications, TECH EXPERT™ provides a cost-effective alternative to the OE:**

### OE Dealer



Replace entire assembly  
\$\$\$\$

### TECH EXPERT™



Replace flap only  
\$\$\$\$

TECH EXPERT's DISA Valve Repair Kit is another example of a complete kit that gives professional technicians the tools they need to replace only the faulty component. In turn, technicians can help their customers avoid entire, expensive repairs.

