



Did You Know?

NAPA Echlin—Jeep Coil Bar

The Jeep coil bar is a **one piece** coil assembly containing three (3) individual coils.

The coil rail must be replaced as an assembly. The bottom of the coil bar is equipped with six individual spark plug boots which are a permanent part of the coil and are not serviced separately.

The coil is bolted directly to the cylinder head. One electrical connector connects all three coils.



IC207

Application: 1999 Jeep

Caution: Inspect the ignition coil bar for cracks and any signs of arcing. Arcing at the secondary end will cause the rubber boots to carbonize which can cause the coil to fail. Replace coil bar if any cracks or signs of arcing are found. **Primary specs only .71 - .88 Ohms**



Application: 2000-06 Jeep

IC399

NAPA Echlin
LOOKS RIGHT. FITS RIGHT. PERFORMS RIGHT.

THE BEAR IS BACK

