

TECH EXPERT™ SOLUTIONS

Tech Expert™ European Solutions



TECH EXPERT™ offers a wide variety of high quality European parts typically bought at the dealer.



TBV700 Turbocharger Bypass Valve

- Audi/VW 1.8T 2005-99
- TECH EXPERT™ uses a stronger 14.4lb spring for improved turbocharger operation




SEP700 Engine Oil Separator

- BMW Vehicles 2000-96, VIO over 300,000
- OE valves freeze, crack, and fail especially in colder weather



EDV700 Electronic Diverter Valve

- Audi/VW 2.0T 2011-05
- VIO over 600,000
- New piston-driven design, eliminates original rubber diaphragm design, preventing boost leaks due to a torn diaphragm



PDC700 Power Distribution Center

- VW Cars 2010-99, VIO over 1.4 million
- Complete drop-in assembly includes terminals, fuses, top cover, and main body



CRK700 Ignition Coil Harness Repair Kit

- Audi/VW 2006-00, VIO over 200,000
- Harness deteriorates over time and breaks when removing the ignition coil
- Repair just the damaged portion of the ignition coil harness instead of replacing the entire harness on 1.8L and 2.7L equipped Beetle, Golf, A4, A6, Allroad, and TT vehicles



VVT500 Variable Valve Timing Chain Tensioner

- Audi/VW Vehicles 2006-01
- VIO over 400,000
- Proven quality solution that includes both the chain tensioner assembly and gasket set that is typically sold separately by the dealer



OLS700 Oil Level Sensor

- BMW Cars & SUVs 2010-95
- VIO over 1.3 million
- Very high OE failure rate, proven quality replacement solution



EXP700 Expansion Tank Service Kit

- VIO over 600,000
- Includes all major components necessary for a complete expansion tank overhaul on automatic transmission equipped BMW E46 3 Series, E83 X3, and E53 X5 vehicles



CCB701 Engine Crankcase Vent Valve CCH700 Breather Hose

- Audi/VW Vehicles, VIO over 300,000 (Valve)
- Audi/VW Vehicles, VIO over 700,000 (Hose)
- Proven quality replacement vent valve and breather hose for 2.0T FSI equipped Passat, Jetta, Eos, A4, TT, and GTI vehicles
- Fixes P1297, P2187, and P2279 DTCs



MRK701 MAF Sensor Repair Kit

- VW Cars & SUVs 2008-00
- Sprinter Vans 2004-02
- 3 SKUs (V38001, V38002, V38003) covering 700,000 vehicles
- Includes new sensor and tamper-proof Torx bit to replace just the failed sensor instead of the entire assembly



Expert Solutions for Professional Technicians™

