



## Tech Expert™ Throttle Position Sensor Repair Kits

**REPLACE  
SENSOR ONLY**



**TPK500**  
Honda (01-89)  
Acura (01-88)  
VIO over 3.2 Million

### Quick Facts



Comes complete with  
gasket, mounting  
hardware, and  
OE-Matching sensor



Replace failed  
sensor only, not  
full throttle body  
assembly



Multiple kits  
available for select  
Honda and Acura  
applications

**TECHEXPERTPARTS.COM**

*Expert Solutions for Professional Technicians™*


## Replace the Sensor, Not the Throttle Body

**The Problem:** On certain Honda and Acura applications, the throttle position sensor cannot be serviced separately through the dealer. Instead, the entire throttle body assembly needs to be replaced, which is an expensive, time-consuming job.

**Our Response:** To provide an alternative for replacing the entire throttle body assembly, Tech Expert's line of Throttle Position Sensor Repair Kits comes complete with everything needed to replace only the failed sensor. Each kit includes an OE-Exact-Match Throttle Position Sensor, a gasket, and all the necessary mounting hardware.

**When the TPS fails on certain Honda/Acura applications, Tech Expert provides a cost-effective alternative to the OE:**

### OE Dealer



Replace entire assembly  
\$\$\$\$

### Tech Expert™



Replace sensor only  
\$\$\$\$

Plus, Tech Expert's Throttle Position Sensors feature high-quality components that ensure precise operation and maintain specific outputs to match OE.

When you add everything up, Tech Expert's Throttle Position Sensor Repair Kit is yet another example of a problem-solving product that helps professional technicians in the bay without sacrificing OE-matching quality.

