



ECHLIN

NEW PARTS SPOTLIGHT

2024

Connectors for Ford Vehicles



EC2707
Cam/Crankshaft Sensor,
EGR Pressure Feedback
Sensor Connector
(2021-2018)



EC3003
Oxygen Sensor
Connector
(2020-2011)




EC3006
Fog Lamp Socket
(2022-2017)



EC3008
Headlight Wiring
Harness Connector
(2019-2012)



EC3010
Power Seat Lumbar
Motor Connector
(2023-2000)



EC3017
Audio Control Module,
Serial Data Gateway
Module Connector
(2023-2011)



EC3018
Acc Pedal Sensor, Cooling Fan Motor,
Heated Seat, Liftgate Release,
Pwr Mirror, Shift Interlock Solenoid,
Turn Signal Light Connector
(2023-2001)



EC3020
Windshield Wiper
Motor Connector
(2023-2002)



EC3026
Cooling Fan
Motor Connector
(2022-2010)



EC3062
Air Bag, Seat Belt
Pretensioner Connector
(2023-2009)



EC3067
Radio Capacitor
Connector
(2023-2004)



EC3071
ABS Control
Module Connector
(2019-2011)



EC3073
Engine Coolant Fan
Motor, Power Window
Motor Connector
(2014-1999)



EC3084
Turbocharger Wastegate
Actuator Connector
(2018-2015)



EC3085
Water Pump, License
Plate Light, Park Assist
Sensor Connector
(2023-2013)



EC3086
Nitrogen Oxide
Sensor Module,
Taillight Connector
(2022-2013)



EC3088
Instrument Cluster,
Liftgate Control
Module Connector
(2019-2005)



EC3089
Diesel Glow
Plug Connector
(2023-2011)



EC3092
Transmission
Bulkhead Connector
(2019-2011)



EC3093
Daytime Running Lamp, Ignition
Coil, Intake Manifold Runner
Control Sensor, Water In Fuel
Sensor Connector
(2022-2010)

For more specific application data, visit NAPAEchlin.com



LOOKS RIGHT. FITS RIGHT. PERFORMS RIGHT.

NAPAEchlin.com

NE11689