

TECH EXPERT™ SOLUTIONS


Tech Expert™ High Pressure Fuel Pump Cam Follower



Tech Expert™ now offers a high-quality direct replacement High Pressure Fuel Pump Cam Follower for 2013-2006 VW/Audi 2.0T.



The low-friction coating on the original units can wear down over time causing excess friction against the cam lobe and high-pressure fuel pump plunger. This can lead to extreme engine damage and an expensive repair. Checking and replacing the cam follower with the Tech Expert™ CMF700 will save money in the long run.




Catastrophic Failure



VW/Audi 2.0T 2013-06
VIO over 1.0 Million

New
Tech Expert™
CMF700



Expert Solutions for Professional Technicians™