



# TECH TIPS



---

## Chrysler Leaky Injector

---

Leaky Injector - 86 Chrysler 2.5L T.B.I. Runs rich and sets Code 52

1. Clean injector with CST-50
2. If injector still leaks after cleaning the injector, will have to be replaced. Check with your local Chrysler dealer for correct part number since there has been a design change in the injector.