



# TECH TIPS



---

## **Honda: Pop-up Headlamps on 1986-1989 Honda Accord**

---

Chafed or broken wires inside the wiring harness to the headlamps may cause problems with the pop-up headlamps on 1986-1989 Honda Accord models.

Symptoms may include inoperative headlamps, failure to change from low to high beams, blown fuses, etc...

Raise the pop-up headlamps, then open up the protective outer wiring harness sheath below the headlamps. Repair any damaged wiring, insulate the repair, then close up the wiring harness sheath. Test the headlamps for operation to verify the fix.

**Always check to make sure that the ground straps are in place and complete connections are made.**

