TECH EXPERT. SOLUTIONS

Tail Light Circuit Boards



High Failure Rate Original Part.

TECH EXPERT[™] offers OE-matching units for the most popular applications.



Molded one-piece unit. TECH EXPERT[™] offers a circuit board with sockets molded directly into the housing to prevent water intrusion into the circuit board.



TCB105

- GM Trucks 2009-02
- Sockets molded into the housing to protect circuit board from water intrusion



TCB104

GM Minivans 2005-97

 Replaces both the LH and RH failed OE units



TCB101

TCB100

- Chevy Trailblazer 2009-04
- Sockets molded into the housing to protect circuit board from water intrusion

Dodge Trucks 2006-03

VIO over 1.5 million

High quality direct replacement

for failed OE circuit boards



TCB102

- GM Trucks 2000-92
- Includes gasket to protect circuit board
- from water intrusion
- VIO over 5.1 million

TCB103

- GM Trucks 2000-92
- Includes gasket to protect circuit board from water intrusion
- VIO over 5.1 million

Third Brake Light Assembly



TECH EXPERT[™] offers a 'brighter-than-OE' LED third brake light. Includes new rubber gasket to prevent water intrusion.

Only need to replace a dry-rotted gasket? TECH EXPERT[™] also offers the gasket separately.





BLA100 Third Brake Light BLG100 Third Brake Light Gasket

Chevy Tahoe/Suburban 2006-03
GMC Yukon/Yukon XL 2006-03

- VIO over 1.4 million





Expert Solutions for Professional Technicians™