



# Did You Know?

## Why Buy From Your Competition?

### NAPA Echlin covers your 2004 Honda Accord

*Fuel Injector*



2-38868

*Stoplight Switch*



SL269

*Oil Pressure Switch*



OP6775

*Clutch Safety Switch*



NS5804

*Headlight Dimmer Switch*



DL6595

*Neutral Safety Switch*



NS6801

*Pressure Regulator*



2-19803

*Ignition Coil-on-Plug*



IC441

*Crankshaft Sensors*




CSS9199



CSS9175

*Coolant Fan Switch*



FS244

*EGR Valve*



2-26640

*Power Door Lock Actuator*



DLA153

*Knock Sensor*



DKS514

*Vehicle Speed Sensor*



VSS784

*Camshaft Sensor*



CSS1119

**NAPA Echlin**  
**LOOKS RIGHT. FITS RIGHT. PERFORMS RIGHT.**

**THE BEAR IS BACK**





# Did You Know?

## Why Buy From Your Competition?

### NAPA Echlin covers your 2004 Toyota Camry

*Ignition Coil-on-Plug*



IC463



IC337

*Throttle Position Sensor*



2-60013

*Fuel Vapor Pressure Sensor*



2-27026

*Ignition Lock Cylinder*




KS6756L

*Fuel Damper Assembly*



2-12507

*Coolant Temperature Sensor*




TS6677

*Coolant Fan Switch*



FS267

*A/C Control Relay*



AR6034

*Fuel Pressure Regulator*



2-19747

*Crankshaft Sensors*



CSS9156



CSS950

*Headlight Dimmer Switch*



DL6577

*Fuel Injector*



2-18093

*Camshaft Sensor*



CSS833

*EGR Valve Temperature Sensor*



2-29385

**NAPA Echlin**  
**LOOKS RIGHT. FITS RIGHT. PERFORMS RIGHT.**

**THE BEAR IS BACK**





# Did You Know?

## Why Buy From Your Competition?

### NAPA Echlin covers your 2004 Nissan Maxima

*Fuel Pump Relay*



AR525

*MAP Sensor*



2-27029

*Oil Pressure Switch*



OP6115

*Windshield Washer Level Sensor*



FLS626

*EGR Valve*



2-26540

*Coolant Temperature Sensor*



TS5583

*Camshaft Sensors*



CSS1094



CSS1095

*Fuel Injector*



2-38852

*Fuel Vapor Canister*



2-29975

*Ignition Starter Switch*



KS6770

*Ignition Coil-on-Plug*



IC479

*Fog Lamp Relay*



AR6060

*Neutral Safety Switch*



NS5597

*Crankshaft Sensor*



CSS9099

*Headlight Dimmer Switch*



HL7061

**NAPA Echlin**  
**LOOKS RIGHT. FITS RIGHT. PERFORMS RIGHT.**

**THE BEAR IS BACK**






# Did You Know?

## Why Buy From Your Competition?

### NAPA Echlin covers your 2004 Hyundai Elantra

*Coolant Temperature Sensor*



TS5734

*Throttle Position Sensor*



2-16732

*Camshaft Sensors*



CSS1161



CSS1131

*Knock Sensors*



DKS696



DKS658

*Crankshaft Sensor*



CSS9228

*Fuel Injector*



2-38876

*Ignition Coil*



IC539

*Ignition Starter Switch*



KS6939

*Headlight Dimmer Switches*



DL6382



DL6380

*Blower Motor Resistor*



BR258

*PCV Valve*



2-9496

NAPA Echlin is your  
one stop for complete  
Import Coverage!

**NAPA Echlin**  
**LOOKS RIGHT. FITS RIGHT. PERFORMS RIGHT.**

**THE BEAR IS BACK**

