




ECHLIN®

WINDOW LIFTS

LOOKS RIGHT.
FITS RIGHT.
PERFORMS RIGHT.

Manual and Power Window Regulators

On average, a person rolls their window up and down 4 to 5 times a day. That's over 1,825 times a year! All NAPA® Echlin® window lift regulators are thoroughly tested and validated for fit, form and function before being added to our product offering. NAPA® Echlin® prides itself on doing the work of validation in house with our library of over 500 automotive doors to make sure your customers aren't doing the work for us.




- Designed to work with original equipment window motors
- Validated for form, fit and function
- Exact drop in replacement
- Select regulators have been redesigned, replacing slides with rollers to extend cable life
- Premium grease for longer life

Common Failures of Power Window Regulators

All NAPA® Echlin® window lift products meet our stringent product validation standards and in many cases offer a design improvement over the OE.



CABLE TYPE



BROKEN CABLE

Cables wear, fray and eventually break disabling the window & damaging other components.



Shear Type



Stripped Teeth

Shear teeth wear and strip disabling the gear components which can also cause the motor to fail.