


Coil-On-Plug Boot / Wire Set Kits

NEW

As wire sets disappear from vehicles, COIL-ON-PLUG technology is an important part of ignition systems. Coil boot replacement is part of maintaining a properly tuned engine. This product category will be at the forefront in the years to come.

- 29 Wire Set & Coil Boot combinations for engines that have both ignition wires and coil boots
- 5 Coil Boot Kits for engines that have different coil boots
- Each kit contains all of the ignition components necessary for a complete tune-up in one package



700547K



Belden® EDGE
PREMIUM SPARK PLUG WIRES



ECHLIN.

NAPA® BELDEN® PART NO.	DESCRIPTION	UNIT DESG	PVQ	JOBBER STD PKG	NAPA CLASS	APPLICATIONS
702511	COP BOOT	EA	4	4	W	Nissan Sentra L4 2.0L, MR20DE Engine 10-07
702515	COP BOOT	EA	6	4	S	Infiniti Q45 4.5L V8 Cyl. 2/93-3/90
702516	COP BOOT	EA	6	4	W	Hyundai Santa Fe 2.7L 09-07, Kia Optima 2.7L V6 08-07
702517	COP BOOT	EA	8	4	W	Chrysler, Dodge, Jeep 4.7L V8 10-08
702518	COP BOOT	EA	6	4	A	Lexus ES350, RX350, RAV4, IS350, Toyota Avalon, Camry, Sienna, Highlander, 3.5L V6 08-05
702519	COP BOOT	EA	6	4	W	Dodge Dakota, Durango, Nitro, Ram 1500, Raider, Jeep Grand Cherokee, Commander Liberty 3.7L V6 11-09
702520	COP BOOT	EA	8	4	W	Ford F Series Pickups 6.2-6 V8 2011
702521	COP BOOT	EA	8	4	W	Lexus V6, Toyota various 2.5L, 3.5L, 4.6L, 5.0L, 5.7L 09-07
702523	COP BOOT	EA	6	4	W	Buick, Cadillac, Chevrolet, GMC, Pontiac, V6 3.6L, 3.0L, 2.8L 11-07
700007K	WIRE SET	EA	1	1	S	Hyundai Accent 4 Cyl. 1.5L DOHC 97-95
700010K	WIRE SET	EA	1	1	W	Toyota Tacoma, 4Runner, T100 5VZFE 6 Cyl. 3.4 04-95
700011K435	WIRE SET	EA	1	1	W	Toyota 6 Cyl. 3.0 Avalon 99-96, Camry 01-96, Lexus ES300 1MZFE 97-96
700011K496	WIRE SET	EA	1	1	W	Toyota 6 Cyl. 3.0 Avalon 99-96, Camry 01-96, Lexus ES300 1MZFE 97-96
700019K	WIRE SET	EA	1	1	S	Toyota 4 Cyl. (5EFE)1.5 - Tercel 99-95, Paseo 99-96
700067K	WIRE SET	EA	1	1	S	Mercedes Benz 6 Cyl. 3.2 C280, E320, SL320 99-95
700109K	WIRE SET	EA	1	1	S	Mazda Protégé 1.6L DOHC 03-99
700115K	WIRE SET	EA	1	1	W	Mazda 4 Cyl. 2.0 Protégé 03-01
700153K	WIRE SET	EA	1	1	W	Mitsubishi Lancer 4 Cyl. 2.0L 03-02, Mirage 4 Cyl. 1.8L 02-97
700163K	WIRE SET	EA	1	1	W	KIA 4 Cyl. 1.8L Sephia 01-98, Spectra 04-00
700208K	WIRE SET	EA	1	1	W	KIA Sportage 4 Cyl. 2.0-3 02-95
700212K	WIRE SET	EA	1	1	W	Hyundai Sonata, Santa Fe 06-99, Kia Optima, Magentis 2.4L DOHC 06-01
700215K	WIRE SET	EA	1	1	W	KIA Sedona 6 Cyl. 3.5 05-02
700258K	WIRE SET	EA	1	1	W	Mitsubishi 4 Cyl. 2.4L SOHC Eclipse, Chrysler Sebring 06-01
700452K	WIRE SET	EA	1	1	S	Mazda 4 Cyl. 1.8 Miata 05-01
700529K	WIRE SET	EA	1	1	S	Mitsubishi Montero 6 Cyl. 3.8L 06-03
700530K	WIRE SET	EA	1	1	S	Mitsubishi Lancer Evolution 4 Cyl. 2.0L. Turbo 04-03
700542K	WIRE SET	EA	1	1	S	Land Rover Freelander 6 Cyl. 2.5L DOHC 05-02
700546K	WIRE SET	EA	1	1	S	Mercedes Benz 2.3 - C230 00-97, SLK230 00-98
700547K	WIRE SET	EA	1	1	W	Dodge Trucks Ram Pickup (Hemi) 8 Cyl. 5.7L 05-03
700548K	WIRE SET	EA	1	1	S	Chrysler 300, Dodge Magnum SRT, Jeep Grand Cherokee, 8 Cyl. 5.7L 2005
700593K435	WIRE SET	EA	1	1	S	Lexus ES300 6 Cyl. 3.0 01-98
700593K496	WIRE SET	EA	1	1	S	Lexus ES300 6 Cyl. 3.0 01-98
700596K	WIRE SET	EA	1	1	S	Lexus GS300 05-98, Lexus IS300 05-01
700597K	WIRE SET	EA	1	1	W	Hyundai XG350 6 Cyl. 3.5L 05-03, Santa Fe 3.5L 06-03, Kia Amanti 3.5L 06-04
700622K455	WIRE SET	EA	1	1	S	Suzuki Esteem 4 Cyl. 1.6 02-99, Swift 4 Cyl 1.3, Vitara 4 Cyl. 1.6 02-99
700622K456	WIRE SET	EA	1	1	S	Suzuki Esteem 4 Cyl. 1.6 02-99, Swift 4 Cyl 1.3, Vitara 4 Cyl. 1.6 02-99
700890K	WIRE SET	EA	1	1	S	Mercedes 280, 320 24V 96-94
9702437K	COP BOOT	EA	1	1	S	Nissan VQ35DE Engine Pathfinder 02-01
9702439K	COP BOOT	EA	1	1	W	Infiniti I30 01-96, Nissan Maxima 01-95 6 Cyl. - Mitsubishi and Hanshin Coils
9702439K1	COP BOOT	EA	1	1	W	Infiniti I30 01-96, Nissan Maxima 01-95 6 Cyl. - Mitsubishi and Hanshin Coils
9702444K	COP BOOT	EA	1	1	W	Honda Passport 3.2L 02-00, Isuzu Axiom, Amigo, Rodeo, Trooper Cyl. 6, 3.5 X 20
9702492K	COP BOOT	EA	1	1	S	Nissan Maxima 3.0L VE30DE 94-92

Contact your local NAPA Auto Parts store for more details

